

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

DV595
East
1/2-1
0.891 mi.
4703 ft.
GETTY
231 NEPTUNE AVE
BROOKLYN, NY 11235
Site 1 of 2 in cluster DV

NY UST
NY Spills
U001836678
N/A

Relative:
Higher

UST:

Actual:
9 ft.

Name: GETTY
Address: 231 NEPTUNE AVE
City,State,Zip: BROOKLYN, NY 11235
Id/Status: 2-146196 / Unregulated/Closed
Program Type: PBS
Region: STATE
DEC Region: 2

Expiration Date: N/A
UTM X: 587874.91380
UTM Y: 4492800.03289
Site Type: Unknown

Affiliation Records:

Site Id: 4229
Affiliation Type: Facility Owner
Company Name: POWER TEST REALTY COMPANY
Contact Type: Not reported
Contact Name: Not reported
Address1: 175 SUNNYSIDE PL
Address2: Not reported
City: PLAINVIEW
State: NY
Zip Code: 11803
Country Code: 001
Phone: (516) 576-9500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 4229
Affiliation Type: Mail Contact
Company Name: POWER TEST REALTY COMPANY
Contact Type: Not reported
Contact Name: Not reported
Address1: 175 SUNNYSIDE PL
Address2: Not reported
City: PLAINVIEW
State: NY
Zip Code: 11803
Country Code: 001
Phone: (516) 576-9500
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 4229
Affiliation Type: Facility Operator
Company Name: GETTY
Contact Type: Not reported
Contact Name: LEONID SCHMERLIS
Address1: Not reported

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 001
Phone: (718) 646-6992
EMail: Not reported
Fax Number: Not reported
Modified By: TRANSLAT
Date Last Modified: 2004-03-04

Site Id: 4229
Affiliation Type: Emergency Contact
Company Name: POWER TEST REALTY COMPANY
Contact Type: Not reported
Contact Name: TOM DICKSON
Address1: Not reported
Address2: Not reported
City: Not reported
State: NN
Zip Code: Not reported
Country Code: 999
Phone: (718) 729-6500
EMail: Not reported
Fax Number: Not reported
Modified By: NRLOMBAR
Date Last Modified: 2009-07-21

Tank Info:

Tank Number: 001
Tank ID: 19139
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 4000
Install Date: 08/01/1974
Date Tank Closed: 04/01/1991
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: 01
Date Test: 04/01/1988
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

J02 - Dispenser - Suction Dispenser

Tank Number: 002
Tank ID: 19140
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 05/01/1949
Date Tank Closed: 04/01/1991
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
A00 - Tank Internal Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser

Tank Number: 003
Tank ID: 19141
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 05/01/1949
Date Tank Closed: 04/01/1991
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser

Tank Number: 004
Tank ID: 19142
Tank Status: Closed - Removed
Material Name: Closed - Removed
Capacity Gallons: 550
Install Date: 05/01/1949
Date Tank Closed: 04/01/1991
Registered: True
Tank Location: Underground
Tank Type: Steel/carbon steel
Material Code: 0009
Common Name of Substance: Gasoline

Tightness Test Method: NN
Date Test: Not reported
Next Test Date: Not reported
Pipe Model: Not reported
Modified By: TRANSLAT
Last Modified: 04/14/2017

Equipment Records:

A00 - Tank Internal Protection - None
B00 - Tank External Protection - None
C00 - Pipe Location - No Piping
D02 - Pipe Type - Galvanized Steel
F00 - Pipe External Protection - None
G03 - Tank Secondary Containment - Vault (w/o access)
H00 - Tank Leak Detection - None
I00 - Overfill - None
J02 - Dispenser - Suction Dispenser

SPILLS:

Name: EMPTY LOT
Address: 231 NEPTUNE AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 9805792 / 1998-08-18
Facility ID: 9805792
Facility Type: ER
DER Facility ID: 74789
Site ID: 80720
DEC Region: 2
Spill Cause: Other
Spill Class: D6
SWIS: 2401
Spill Date: 1998-08-10
Investigator: MMMULQUE
Referred To: Not reported
Reported to Dept: 1998-08-10
CID: 371
Water Affected: Not reported
Spill Source: Gasoline Station or other PBS Facility
Spill Notifier: Other

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: 1998-08-18
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Date Entered In Computer: 1998-08-10
Spill Record Last Update: 1998-10-26
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was
MULQUEEN FALSE REPORT. FORMER GAS STATION, TANKS REMOVED UNDER DEC
SUPERVISION. 87-10929 SPILL CLOSED. PORTION OF BLDG BEING DEVELOPED,
BUT NO EXCAVATION ON PREMISES. "

Remarks: "GAS STATION WAS KNOCKED DOWN AND LAUNDRYMAT IS GOING TO BE BUILT ON
THE SITE - COUNCILMAN'S CONSTITUENTS WORRIED THE SITE WAS NOT CLEANED
PROPERTY AND GAS WAS NOT REMOVED TOTALLY - PLEASE INVESTIGATE."

All Materials:

Site ID: 80720
Operable Unit ID: 1067012
Operable Unit: 01
Material ID: 316977
Material Code: 0008
Material Name: diesel
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported

Site ID: 80720
Operable Unit ID: 1067012
Operable Unit: 01
Material ID: 316978
Material Code: 0009
Material Name: gasoline
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported